

# A hot steam leak during baking of ASDEX Upgrade – consequences and lessons learned

A. Herrmann, V. Rohde, G. Schall, M. Balden, D. Bösser, K. Hegele, K. Hunger, J. Stober, T. Vierle, S. Vorbrugg,  
and the ASDEX Upgrade team

*Max-Planck-Institut für Plasmaphysik, D-85748 Garching, Germany*

ASDEX Upgrade is a midsize tokamak operated since 1991. A scheduled maintenance and enhancement shut down is done about once a year. After pump down and leak search a baking procedure is started to condition the vacuum vessel for plasma operation. During operation the vacuum vessel and all in-vessel components are water cooled. This cooling system is also used for baking with hot water at 150°C. During one of these regular baking periods a hot steam leak appears in November 2017. The detection of the leak has triggered a controlled cool down scenario. Nevertheless, between the appearance of the leak and the identification and closing about 100 l water escaped during the controlled cool down from 150°C to 65°C into the torus. A fraction of the hot water was distributed as steam all over the torus and condensed at the coldest parts of the vessel, preferentially in remote ports. In addition, the steam interacts with boron containing layers. The resulting acid steam caused additional erosion.

The paper presents details of damages, actions taken to remove them as well as measures taken to avoid a future steam leak.

Keywords: ASDEX Upgrade, steam event, vessel baking, safety




Fig. 1 Chronology of the steam event, the shutdown and restart.

## 1. Introduction

ASDEX Upgrade is a midsize tokamak operated since 1991[1]. A scheduled maintenance and enhancement shut down is done about once a year. After pump down and leak search a baking procedure is started to condition the vacuum vessel for plasma operation. During operation ASDEX Upgrade is water cooled with two separate cooling circuits for the vacuum vessel and all in-vessel components, respectively. This cooling system is also used for baking with hot water at 150°C at 12,5 bar.. During one of these baking periods a hot steam leak appeared in November 2017. The detection of the leak has triggered a controlled cool down scenario. Nevertheless, between the appearance of the leak and the identification and closing (about 100 l water) escaped during the controlled cool down from 150°C to 65°C into the torus. A fraction of the hot water was distributed as steam all over the torus and condensed at the coldest parts of the vessel, preferentially in remote ports. In addition, the steam interacts with boron containing layers. The resulting acid steam caused additional erosion [2].

After opening the vessel for man-access salt like remnants and rust were identified.

This paper reports on the damages, the actions to re-establish operation and the measures taken to avoid future steam events.


## 2. Steam event

### 2.1. Chronology

In November 2017, a small water leak occurred during plasma experiments at the divertor manipulator (DIM-II) at about 70°C (Fig. 1). About 10 liters of water were found in the lower divertor region nearby the location of DIM-II. Removing the water and drying required man access for 2 days. After closing the vessel, the routine restart for vessel conditioning was started - leak testing followed by baking the vessel at 150°C for about a week, depending on the water partial pressure. After about 3 days baking, a small water leak was detected and the controlled cool down with about 6K/hour was started. A low cool down rate is used to allow temperature equilibration between different sections and in-vessel components, mainly for thermo-mechanical stress reduction. The chronology of the baking is shown in Fig. 2.

Unfortunately, during the cool down at about 90°C, the water leak was enlarged. After detecting a significant loss of water from the reservoir, the in-vessel water baking system was switched off at about 65°C. The amount of water escaped into the vessel was estimated from the loss of water from the water reservoir to about 100 l.

The steam event happens about two months before a scheduled opening so that the damage repair and the scheduled work could be done in parallel, as indicated in Fig. 1.



80

81 Fig. 2 Chronology of the steam event.

82 **2.2. Steam event - findings**

83 A first look onto the vessel and the large vacuum  
 84 windows after entering the experimental hall has already  
 85 shown the problem. A fraction of the hot water was  
 86 distributed as steam all over the torus and was condensed  
 87 at the coldest parts of the vessel.


88 Venting and opening the vessel for man access gave  
 89 a first insight in the consequences of the steam event:

- 90 • Condensed water all around the torus,  
 91 preferentially in (colder) remote parts.
- 92 • Salt like remnants originating from the interaction  
 93 of the steam with deposited layers resulting from  
 94 plasma wall interaction and boronization [3] of the  
 95 first wall. During the experimental campaign 2017  
 96 about 60 g of boron was deposited onto the inner  
 97 surface of about 50 m<sup>2</sup>.
- 98 • Rust, in particular around welding seams.

99 **2.3. Steam event – origin**

100 A small copper seal deep in an NBI-port duct was  
 101 identified as the origin of the leak. The NBI port duct is  
 102 water cooled to remove the heat due to reionization losses  
 103 in the duct. The VCR<sup>®</sup> (metal gasket face seal) like seal  
 104 was hidden behind a protection plate Fig. 3. It was never  
 105 touched over more than 10 years and more than 26 baking  
 106 cycles.

107 Microscopic inspection revealed strong erosion of the  
 108 copper seal and a gap causing the leak, see Fig. 3 and Fig.  
 109 1 in [2]. The erosion of the copper is attributed to the  
 110 acidic pH-value of pH=5 found by analysing the water  
 111 from the baking circuit.  
 112



113

114 Fig. 3 (left) VCR<sup>®</sup> (metal gasket face seal) like seal in the NBI  
 115 duct cooling pipes behind a protection plate (removed), (right)  
 116 photo of the Cu-seal and the leak location (arrows).

117 Acidic water is not used by intention. Usually  
 118 deionized water is used for the cooling of the in-vessel  
 119 structure to ensure a low electrical conductance of the  
 120 water. A conductance below 5μS/cm is required to  
 121 avoid an electrical by-pass over the insulating gaps  
 122 installed in the water circuits to minimize forces due to  
 123 electrical currents induced during disruptions.  
 124 Unfortunately, the deionized water reacts with CO<sub>2</sub>  
 125 from air at the baking temperature of 150°C.

126 **3. Actions and repair work**

127 The in-vessel inspection and the identification of the  
 128 leak revealed that:


- 129 1. Water can be anywhere in the vessel. Remote  
 130 components can be particularly affected.
- 131 2. All copper seals in the water circuit might  
 132 suffer from erosion.

133 As a consequence, the lower and upper divertor as well  
 134 as the protection tiles of the inner column were  
 135 disassembled to replace all copper seals in the in-vessel  
 136 water cooling system and to give access to remote areas  
 137 for inspection and cleaning (magnetic pick-up coils,  
 138 vacuum bellows).

139 During baking all valves between the AUG vessel  
140 itself and diagnostics with a separate pumping systems  
141 are closed. The ECRH valve for the ECRH window  
142 protection was open. The steam was condensed at these  
143 remote regions near to the vacuum barrier.

144 Before the dedicated refurbishing of diagnostics and  
145 other remote components was started, the main vessel  
146 was cleaned by using a combination of steam and  
147 vacuum cleaning. This way salts and other remnants  
148 could be removed, whereas the rust removal was  
149 supported by mechanical methods, see Fig. 4.

150



151

152 Fig. 4 (left) Combination of steam and vacuum cleaning. (right)  
153 Situation before and after the vessel cleaning.


### 154 3.1. ECRH damages and repair.

155 Between the gate valves and the ECRH-windows,  
156 short Aluminum wave guide sections are installed as  
157 inserts into the stainless-steel ports. The intermediate  
158 volumes were filled with aggressive water. Six systems  
159 had to be completely disassembled up to the gate valves.  
160 Fortunately, the copper brazings of the diamond windows  
161 did not show signs of erosion nor did the absorption at  
162 140 GHz of the diamond change significantly. Corrosion  
163 was observed in the gate valves, the inserted Al wave  
164 guides and some in-vessel gearings. These were only  
165 cleaned, not replaced.

### 166 3.2. Refurbishing of vacuum valves

167 A significant amount of water and salts were detected  
168 inside diagnostic ports and the corresponding valves. To  
169 refurbish the components the adapter between the AUG  
170 vessel and the corresponding diagnostic was  
171 disassembled to get access to the valve corpus. The  
172 components were steam and vacuum cleaned, dried and  
173 reinstalled. A typical installation is shown in Fig. 5

174



175

176 Fig. 5 (left) View into a diagnostic port with a closed valve  
177 showing condensed water. (right) External view to the  
178 diagnostic tubes and the valve for diagnostic separation.

### 179 3.3. Flanges with electrical feed troughs

180 Nearly all flanges used for electrical signals in  
181 particular for bolometer diagnostics and vessel  
182 protection systems, such as thermocouples and strain  
183 gauges were inspected. A typical finding is shown in  
184 Fig. 6. The steam was interacting with layers and  
185 deposits of the vessel and the condensed water was  
186 polluted by boron and boron salts. This aggressive water  
187 has dissolved Molybdenum pins of the vacuum feed-  
188 through and results in leaks in many flanges. For  
189 refurbishing, the flanges were disassembled, afterwards  
190 sand-blasted, cleaned in an ultra-sonic bath, dried and  
191 finally leak tested. This procedure was applied to more  
192 than 85 flanges. 25 out of them showed a leak and were  
193 replaced by new ones.

194



195

196 Fig. 6 Flange with electrical feedthroughs before cleaning.



197

198 Fig. 7 (left) 5 pin electrical feed through showing the corrosion  
199 at the Molybdenum pins (see also fig. 4 [2]). (right)  
200 Refurbished feed-through.

### 201 3.4. Rust

202 AUG is made from stainless steel and rust is initially  
203 not expected. Nevertheless, it was found on both sides  
204 of welding seams where the material structure is  
205 modified due to the welding. Rust was predominantly  
206 found in the pump ducts (Fig. 8) that were  
207 manufactured by a company different from the vacuum  
208 vessel manufacturer.

209




210

211 Fig. 8 Rust at both sides of a welding seam in a pump duct.

212 More critical was the existence of rust in the lower  
213 part of the 1.2 mm thin bellows of the vacuum barrier  
214 connecting the eight otherwise electrically insulated  
215 AUG octants (Fig. 9). Pitting corrosion could result in a  
216 leak in a component that can't be replaced. The rust was



217 detected occasional in folds of the bellows and not at the  
 218 welding seems itself. The origin were small particles  
 219 laying in the bottom of the folds. SEM analysis of  
 220 particles reveals that they contain iron, either in metallic  
 221 or oxidic state. The source of these small particles was  
 222 identified. They were fallen down during an  
 223 installation/drilling years ago.  
 224 In these places the particles were taken out and the rust  
 225 was mechanical removed, followed by cleaning with  
 226 purified water and drying. This way the rust could be  
 227 removed completely as shown in Fig. 9.  
 228




229  
 230 Fig. 9 (left) Bellow with deposited rust in a single fold. (right)  
 231 Bellow after refurbishing.

232 Pitting corrosion cannot be completely excluded for  
 233 the remaining rust in pump ducts that are not, or only with  
 234 huge effort, accessible. That's why a few flanges were  
 235 identified that will be opened at the end of scheduled shut  
 236 downs to monitor a potential pitting corrosion. Control  
 237 inspections done during the two subsequent shut downs  
 238 revealed no further evolution of rust.


#### 239 4. Restart

240 After more than six-month shutdown used for new in-  
 241 vessel installations and refurbishing components  
 242 damaged by the steam event, the vessel was closed and  
 243 pumped down. This first pump down revealed significant  
 244 leaks in the order of  $5 \times 10^{-2}$  mbar.l/s. The leaks were  
 245 caused by flanges with Helicoflex seals. Standard seals  
 246 are CF-seals at AUG. Helicoflex seals are used for the  
 247 large rectangular horizontal port flanges. But they were  
 248 also used during the assembly of AUG to extend the  
 249 upper and lower vertical ports. Such, the vacuum barrier  
 250 was moved to a position outside the poloidal field support  
 251 structure. These extensions tubes were assembled before  
 252 the poloidal field coils and their support structure. The  
 253 Helicoflex seals were never touched after AUG came into  
 254 operation in 1991. The access, in particular to the inner  
 255 most flange is only possible through a 10 cm wide gap,  
 256 whereas the flange itself is about 80 cm below the support  
 257 structure. Tools with extensions were used to open the  
 258 flanges and to inspect and remove the seals (see Fig. 10).  
 259 Afterwards the flange surfaces were cleaned and polished  
 260 using extensions. In addition, the Helicoflex flange at the  
 261 extension tube was modified to provide a narrow sheet  
 262 metal strip that holds the gasket in position during  
 263 assembly.



264  
 265 Fig. 10 (left) Top view of AUG during assembly, before the  
 266 installation of the poloidal field coils and the support structure.  
 267 The long extension tubes are already mounted. (middle) CAD  
 268 view with the poloidal field support structure. The critical  
 269 ports are placed inside the inner triangles with about 10 cm  
 270 gap size. (right) Photo of the real situation on top of AUG.

271 The Aluminium material of the Helicoflex seals  
 272 show a strong erosion resulting in pitting, as shown in  
 273 Fig. 11. The vertical ports at AUG are mostly used for  
 274 electrical cables but also for optical fibres. Whereas  
 275 electrical cables can be disconnected at the flange,  
 276 optical fibres cannot. Removing them would require  
 277 man access to the vessel. Instead of replacing all  
 278 Helicoflex seals, seals with leaks were identified and  
 279 replaced iteratively until the leak rate was below  $1e^{-7}$   
 280 mbar.l/s. Three pump downs and the replacement of 23  
 281 seals were necessary (see Fig. 1).  
 282



283  
 284 Fig. 11 Helicoflex seal. (clockwise, starting upper left).  
 285 Scheme of a Helicoflex seal, Flange showing deposits,  
 286 microscopic picture of a seal with whole and deposited salt.

287 The third pump down was also used for a short  
 288 baking to make sure that the thermal expansion due to  
 289 the baking is not causing additional leaks at pre-  
 290 damaged non-replaceable seals.

291 The good vacuum after the third seal replacement  
 292 cycle allowed detecting leaks in the  $1e^{-7}$  mbar.l/s range.  
 293 At this leak level 4 essential feed throughs for magnetic  
 294 diagnostics were identified as to be replaced due to  
 295 leaks. Preparing the new flanges and installation  
 296 required about a month. The 'final' pump down was  
 297 started at the end of August 2018. After baking, first  
 298 technical discharges were performed mid of September.

299 About 6 flanges with a tolerable leak rate were  
 300 replaced later during the shutdown in 2019.

## 301 5. Actions to avoid and mitigate future steam 302 events

303 Different measures were taken and operation  
304 procedures were modified to avoid steam events, or at  
305 least to mitigate the effects in future.

306 Erosion of copper seals will be minimized by  
307 increasing the water pH to  $\text{pH} = 8.5$  by adding NaOH  
308 during baking.

309 The pressure for the routine leak testing before the  
310 infill of water will be increased from 10 bar to 20 bar.

311 A leak during baking at elevated temperature cannot  
312 be generally excluded. To mitigate the consequences the  
313 control logic was modified. In case of a leak the baking  
314 of in-vessel components will be stopped if a pressure  
315 increases to about  $p \approx 10^{-1}$  mbar is detected.  
316 Subsequently, the in-vessel water-cooling system will be  
317 emptied and the vessel will be cooled down by using the  
318 external vessel cooling only. Venting the torus to 500  
319 mbar  $\text{N}_2$  forces the cooling of in-vessel components by  
320 heat convection.

321 In case that steam escapes into the vessel, it will be  
322 dried by pumping and purging shortly after the event.

## 323 6. Summary

324 A steam event happened about two months before a  
325 scheduled opening due to a water leak during baking.

326 That the event happens before a scheduled opening  
327 was a stroke of luck, as the repair work could be carried  
328 out in parallel with the planned enhancements work.

329 The regular restart required three additional months  
330 to identify and fix leaks caused by erosion due to the  
331 steam. About 8 months shutdown were necessary to  
332 recover from the failure of a small copper seal in an NBI  
333 port.

334 A water leak event, and in particular a steam event, is  
335 the concern for the reliable operation of fusion  
336 experiments and adequate measures to mitigate the risk  
337 are taken, see e.g.[4]. For AUG new measures have been  
338 defined to minimize the risk of a steam event and to  
339 prevent damages in future:

- 340 • The pH value of the hot water will be increased to  
341  $\text{pH} = 8.5$  to avoid Cu erosion.
- 342 • The reaction on a steam event is optimized to reduce  
343 the amount of escaping water.
- 344 • Prompt conditioning/drying of the vessel is  
345 recommended to avoid further erosion in remote  
346 areas during the shutdown period.

347 No additional leaks due to erosion were observed  
348 during the following experimental campaigns and shut  
349 downs.

## 350 Acknowledgments

351 The work leading to this article was funded by the European  
352 Atomic Energy Community and is subject to the provisions of the  
353 European Fusion Development Agreement. This work has been carried  
354 out within the framework of the EUROfusion Consortium and has  
355 received funding from the Euratom research and training programme  
356 2014-2018 and 2019-2020 under grant agreement No 633053. The  
357 views and opinions expressed herein do not necessarily reflect those of  
358 the European Commission.

## 359 References

- 360 [1] A. Herrmann, (Guest editor), Special Issue on  
361 ASDEX Upgrade, Fusion Science and Technology, 44  
362 (2003) 1-747.
- 363 [2] V. Rohde, A. Herrmann, M. Balden, D. Bösner, K.  
364 Hunger, G. Schall, M. Uhlmann, T. Vierle, Recovery  
365 from a hot water leakage at the tokamak ASDEX  
366 upgrade, Fusion Eng. Des., 157 (2020) 111630.
- 367 [3] V. Rohde, R. Dux, A. Kallenbach, K. Krieger, R.  
368 Neu, Wall conditioning in ASDEX Upgrade, Journal of  
369 Nuclear Materials, 363-365 (2007) 1369-1374.
- 370 [4] A. Martinez, F. Samaille, M. Chantant, J.C.  
371 Hatchressian, Water leak localization and recovery in  
372 Tore Supra, Fusion Engineering and Design, 82 (2007)  
373 1989-1995.